



TIGRIS Aquatic Services LLC
PO Box 159
Delaware Water Gap, Pennsylvania 18327
Tel: 888-243-0891

Customer: Colony Lakes Home Owners Association	Work Order: 35910139
328 Jennings Rd Manahawkin, New Jersey 08050 Contact: John MacNeil Phone: 6092901612	Lake/Pond/Wetland/Terrestrial Treatment Service Technician: Jeff Horn Date of Service: 7/8/26

SITE NAME: "Colony Lakes - Timber Lake"

Comments:

The lake supports dense patches of Nitella well below the surface scattered throughout the basin. The clarity has dropped, most likely do to the heavy rain. The lake is a bit turned up but not turbid. Survey only.

Water Level		Aesthetic Appearance		Fish / Wildlife	
Full Pool		Good		Geese - Current Activity	
Aquatic Vegetation Identified			Extent of Aquatic Vegetation		
Nitella			Spotty		
Method of Application					
Airboat					
DO (mg/l)	Secchi Depth (Feet)		pH (SU)	Water Temp (°F)	Hardness (mg/l)
6.6	4		7	81.86	60
Product Used			EPA #		
N/A			N/A		

SITE NAME: "Colony Lakes - Colony Lake"

Comments:

The lake supports dense patches of Nitella well below the surface scattered throughout the basin. Observed one stem of coontail. The horned pondweed found throughout the lake was nearing the surface in approximately two acres and was scattered throughout the basin in dense patches.

Water Level		Aesthetic Appearance		Fish / Wildlife	
Full Pool		Good		Geese - Current Activity	
Aquatic Vegetation Identified			Extent of Aquatic Vegetation		
Nitella hornd pondweed Coontail			Spotty Spotty Trace		
Method of Application					
Airboat					
DO (mg/l)	Secchi Depth (Feet)		pH (SU)	Water Temp (°F)	Hardness (mg/l)
6.75	6		6.75	79	60

Product Used	EPA #
Aquastrike	70506-302

COMPLETION FORM

Comments: A treatment was performed on Colony Lake to control the horned pondweed.

Thank you for your business!

